

PUBLIC HEALTH INSPECTION NEW YORK, 31ST JULY 2001

STATEMENT OF CORRECTIVE ACTION

XV. A TOPED. CX/C/DYDA #		
POTABLE WATER SYSTEM		
On several occasions the charts were not changed at 24-hour increments, including one occasion where it ran for 48 hours. Action: SCE Alarm system now set up for reminder to change charts daily at noon. Additional training has been taking place. Item Deleted		
Alarm system now set up for reminder to change charts daily at noon.		
fitted. Item Deleted POOLS/SPA'S		
Ant-vortex drain covers for the pool are on order. Action: SSM On Order, Awaiting delivery. Anti-vortex drain covers fitted. Item Deleted		

FAN ROOM		
4 Ref. 41 DPV 0	A condensate pan area in one of the Fan Rooms exam mould. Action:	ined was soiled with sediment and
	SSM Fan room cleaned	Item Deleted

	ran room cleaned tem Deleted		
<u>LIDO</u>			
5	Food soil was found on cleaned food service items/cookware/mixer head/soft serve machine		
Ref. 26	gasket.		
DPV 0	Action:		
Critical			
	All food service items have been cleaned and staff re-instructed in correct procedures.		
I IDO DA	VILLION GRILL		
LIDO I A	VILLION GRILL		
6	Heavy grease accumulation was noted in the exhaust ventilation trunk duct.		
Ref.33	Action:		
DPV 1	SSM		
DI VI	Part of bi annual cleaning process. Item Deleted		
FOOD SE	CRVICE GENERAL		
1002 82	ATTOE GENTLAND		
7	The decks were in disrepair throughout the food service areas.		
Ref.33	Action:		
DPV 1	SSM		
	Ongoing maintenance.		
	Several areas repaired over the last month.		
8	The deckheads and bulkheads had difficult to clean features such as gaps and loose profile		
Ref.33	strips throughout the food service areas.		
DPV 1	Action:		
	SSM		
	Ongoing maintenance.		
9	The food surfaces of equipment such as ovens, salamander units and refrigerators had		
Ref. 20	difficult to clean features such as gaps, open seams and corroded metal surfaces.		
DPV 2	Action:		
	SSM		
	Ongoing maintenance.		
10	The non-food contact surfaces of equipment such as ovens, grills, refrigerators, tilt pans, tilt		
Ref. 21	skillets and fryers were difficult to clean to gaps, open seams, Philips head screws and flat		
DPV 1	head screws.		
	Action:		
	SSM		
	Ongoing maintenance. Stainless steel screws to be fitted.		
	Caps for screws fitted as necessary. Ongoing maintenance.		
11	Slight corrosion was noted in the ice/water contact surfaces of the upper compartments in		
Ref. 20	the new Manitowoc ice machines. Corroded flat head screws were also noted in these		
DPV 2	compartments.		
	Action:		
	SSM		
	Stainless steel screws to be fitted.		
	Screws were delivered in Southampton on the 10 th September. Item Deleted		

MAURE	<u>rania</u>		
12	The wall covering behind the double wait station near table 262 had open seams.		
Ref. 33	Action:		
DPV 1	SSM		
	Wall covering sealed. Item Deleted		
MAURET	TANIA GALLEY ENTERANCE		
13	A bucket with soiled water was on the deck with wiping cloths in it.		
Ref. 25	Action:		
DPV 0	Sanitation Officer		
	All staff instructed to change water in buckets when necessary. Item Deleted		
MAURE	TANIA POTWASH		
14	The hot water sanitising compartment was not provided with a basket.		
Ref. 22	Action:		
DPV 0	F&B		
	Sinks have been measured for baskets.		
	Quote has been received for 1500 pounds. In Progress		
15	A few previously cleaned pans were soiled and stored as clean.		
Ref. 26	Action:		
DPV 0	F&B		
Critical	All equipment has been cleaned and staff re -instructed in correct procedures.		
	Deleted.		
16	Two paddles were cracked making them difficult to clean.		
Ref. 20	Action:		
DPV 2	F&B		
	Paddles were discarded Item		
	Deleted.		
MAURET	TANIA DISHWASH		
17	A short curtain was noted between the wash and rinse compartments.		
Ref. 22	Action:		
DPV 0	SSM		
	Requirement to be clarified as curtain is as per manufacturer's recommendation which is		
MAURET	approved. FANIA HOT GALLEY		
18 Ref. 16	Eggs just cracked were tested at 38 - 47°F.		
DPV 0	Action:		
DL A O	F&B Policy on time control messages has been implemented and is decommented.		
10	Policy on time control measures has been implemented and is documented.		
19 Ref. 16	The filling for the omlets were not kept at or below 41°F. Ham 66°F, Lox 57°F, cheese		
DPV 5	60°F, egg whites 71°F and cooked mushrooms at 70°F.		
Critical	Action: F&B		
Cincai			
20	Policy on time control measures has been implemented and is documented. Two food handlers were wearing watches while handling food.		
Ref. 14	Action:		
	F&B		
DPV 0	F&B		

	All food handlers have been instructed that other than a plain wedding band no watches or jewellery can be worn in a food handling area. Item Deleted
MAURET	ANIA COLD LARDER
21 Ref. 14 DPV 0	Two food handlers were wearing watches while handling food. Action: F&B All food handlers have been instructed that other than a plain wedding band no wetches or invallence can be wen in a food in a food handling area. Item Deleted
22 Ref.16 DPV 5	watches or jewellery can be won in a food in a food handling area. Item Deleted Plated salmon in the service refrigerator was tested at 46° - 52°F. The back up salmon was tested at 42°F. Action: F&B Policy on time control measures has been implemented and is documented.
23 Ref.16 DPV 5	The English cheddar on the plating table was tested at 51°F. This was a very small amount of cheese that was noted out of temperature. Cold cuts on the table were tested at 45° - 47°F. Action: F&B Policy on time control measures has been implemented and is documented.
MAURET	ANIA PASTRY
24 Ref. 33 DPV 1	The deck under refrigerator unit RO20 was soiled. Action: Sanitation Officer
MAIN GA	Area deep cleaned. Item Deleted LLEY ENTERANCE
25 Ref. 40 DPV 0	An open door was noted near the main galley entrance adjacent to the bakery. This door was not protected against vermin entry. Action: SSM Signs have been placed advising (Clase door?)
MAIN GA	Signs have been placed, advising "Close door" Item Deleted LLEY BAKERY STORE ROOM
26 Ref. 21 DPV 1	The shelves were not constructed of an easy to clean material. Action: SSM Shelving to be replaced as part of 4 year plan. Ship's Services Manager awaiting quote. In Progress
27 Ref. 33 DPV 1	The deck under refrigeration unit RO32 was soiled. Action: Sanitation Officer Area deep cleaned. Item Deleted
MAIN GA	LLEY ICE CREAM
28 Ref. 20 DPV 2	The ice cream machine mixing wells and the inner surfaces of the doors were worn on both units. Action:

	agy.		
	SSM		
	Ongoing maintenance		
MAIN GA	LLEY CORRIDOR		
20	A 11 (c) 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
29 D-f-29	A cable cutter and an electric plumbing snake were stored in the galley corridor near the		
Ref. 38	bakery.		
DPV 0	Action:		
	SSM		
NA DI GA	Items removed. Completed		
MAIN GA	LLEY POTWASH		
30	A basket was not provided for the hot water sanitising compartment.		
Ref. 22	Action:		
DPV 0	F&B		
21 . 0	Sinks have been measured for baskets		
MAIN GA	LLEY POTWASH STORAGE		
- MARIN GA	A CA TITADIA DA CARIACIA		
31	The base of a blender was encrusted with drink residue. The blender was stored as clean.		
Ref. 26	Action:		
DPV 0	Sanitation Officer		
Critical	Equipment cleaned and staff re-instructed on correct procedures. Item Deleted		
MATNICA	TIEV CALAD		
MAIN GA	LLEY SALAD		
32	Provide access under the preparation sink so that it can be verified that there is an indirect		
Ref. *	connection to the waste water system.		
DPV 0	Action:		
	SSM		
	Panels removed Item Deleted		
MAIN GA	LLEY ROOM SERVICE		
	-		
33	Tuna salad in the under counter refrigerator was tested at 46°F.		
Ref. 16	Action:		
DPV 0	F&B		
Critical	Policy on time control measures has been implemented and is documented.		
PRINCES	S GRILL		
34	The deck under refrigeration unit RO71-72 was heavily soiled.		
Ref. 33			
DPV 1	Action: Sanitation Officer		
DIVI			
CADONILA	Area deep cleaned. Item Deleted		
CARUNIA	A PASTRY SERVICE		
35	The ice cream freezer gaskets were split.		
Ref. 21	Action:		
DPV 1	SSM		
	Gaskets replaced. Item Deleted		
PRODUCTION AREA			
26	Important and the state of the		
36	The food in the blast chiller section of the walk in unit under the evaporator was not		
Ref. 19	covered. Condensate was noted on the evaporator.		
DPV 2	Action:		
	F&B		

 $QE2 - 31st \ July \ 2001 \quad 9/17/2001$

	Staff instructed to cover all food and not to place items of food under the
OHEENIG	evaporator. Item Deleted
QUEEN'S	S GRILL POTWASH
37	The hot water sanitising compartment was not provided with a basket.
Ref. 22	Action:
DPV 0	F&B
DI V O	Sinks have been measured for baskets. In Progress
	Sinks have been incusared for business.
CREW G	ALLEY
38	Old grease residue was noted on the chute of the grill.
Ref. 27	Action:
DPV 0	Sanitation Officer
	Grill cleaned and staff re-instructed on correct procedures. Item Deleted.
CREW DI	SHWASH_
39	The final rinse thermometer registered a temperature of greater than 220°F.
Ref. 24	Action:
DPV 0	SSM
Critical	Adjustment made -Thermometer recalibrated. Item Deleted
CREW PO	<u>DTWASH</u>
40	The hot water sanitising compartment was not provided with a basket.
Ref. 22	Action:
DPV 0	F&B
	Sinks have been measured for baskets. In Progress
CONCES	SIONAIRE MESS
41	The sneeze guards in this mess were not adequate to protect the food.
Ref. 19	Action:
DPV 2	SSM
	Sneeze guards on order. Item Deleted
CREW M	<u>ESS</u>
42	An ice machine was present in this mess. Crewmembers dispensed their ice out of the ice
Ref. 19	bin of the ice machine.
DPV 2	Action:
	F&B
	Ice dispensing machine is on order Order Number 8U0699.
43	The plastic moulding around the door frame was cracked in refrigeration unit RO89.
Ref. 20	Action:
DPV 2	SSM
	Replaced Item Deleted
	Completed
44	A loaf of bread was placed on a cutting board for crewmembers to cut their own bread
Ref. 19	without any provision made so that this can be done in a sanitary manner.
DPV 2	Action:
	F&B
	All bread pre-sliced and placed in a covered container. Item Deleted

OFFICER	R'S DISHWASH		
45 Ref. 22	The final rinse pressure at the dishwash unit was approximately 10 psi where the manufacturer recommended 15 –25 psi.		
DPV 0	Action:		
	SSM		
	Pressure brought back to correct range. Item Deleted Completed		
OFFICER	R'S GALLEY		
46	Seared steaks in hot hold cabinet HB001 were tested at 108°F.		
Ref. 16	Action:		
DPV 5 Critical	F&B Policy on time control massages has been implemented and is decomposed.		
	Policy on time control measures has been implemented and is documented. ONS GENERAL		
47	Pallets were placed in the provision rooms whereby crewmembers had to walk on the same		
Ref. 19	pallets food was stored on to either store food or obtain food.		
DPV 2	Action: $F \& B$		
	Ongoing project. All permanent wooden pallets will be replaced with plastic pallets, walkways have been included when laying down new pallets. In Progress		
PROVISI	ONS BOX 2		
48	Cut wheels of gruyere cheese were stored uncovered in this unit.		
Ref. 19	Action:		
DPV 2	F&B Cheese now placed in a plastic container with lid. Item Deleted		
PROVISI	ONS GENERAL		
49	Painted wooden pallets and a few unfinished wooden pallets were noted in the provision		
Ref. 21	rooms.		
DPV 1	Action:		
	F&B Ongoing project to replace existing wooden pallets with durable plastic.		
PAVILLI			
50	Cans of soda were stored under the utility sink waste line.		
Ref. 19	Action:		
DPV 2	F&B		
	Items removed and stored accordingly. Item Deleted		
<u>CHART</u>	ROOM BAR		
51	A vented check valve was not provided at the carbonation unit.		
Ref. 08	Action:		
DPV 0	SSM Complete overhaul in refit.		
	Item fitted. Item Deleted		
CHART	ROOM PANTRY		
52	Wash hands frequently signs were not provided at the hand wash stations.		
Ref. 30	Action:		
DPV 0	F&B		

	Signs in place	Item Deleted	
GOLDEN LION BAR			
53	A wash hands frequently sign was not provided at the hand wash station.		
Ref. 30	Action:		
DPV 0	F&B		
	Signs in place	Item Deleted	
CHART R	ROOM BAR		
54	The hand wash stations for this were located in adjacent area	as that required passage	
Ref. 29	through doors that were normally closed when the bar was open.		
DPV 0	Action:		
Critical	F&B		
	Door kept open by means of latch	Item Deleted	
MEDICAL			
55	Gastrointestinal illness report was not recorded for a late June to early July cruise.		
Ref. 01	Action:	-	
DPV 0	PMO		
Critical	Completed. Report of Gastrointestinal records are held onboard.	Item Deleted	